





| Ref.  | A   | B   | C   | ⚖️   |        |        |
|-------|-----|-----|-----|------|--------|--------|
| 9120  | 200 | 210 | 280 | 5,5  | 912031 | 912050 |
| 9120L | 380 | 200 | 280 | 16,5 | 912031 | 912060 |
| 9122  | 200 | 260 | 330 | 9,0  | 912031 | 912050 |
| 9122L | 380 | 250 | 330 | 11,0 | 912031 | 912060 |
| 9124  | 200 | 340 | 420 | 7,0  | 912031 | 912050 |
| 9124L | 380 | 340 | 420 | 12,0 | 912031 | 912060 |
| 9130  | 380 | 340 | 440 | 14,0 | 131731 | 913050 |
| 9132  | 380 | 455 | 550 | 15,5 | 131731 | 913050 |
| 9134  | 380 | 555 | 650 | 19,5 | 131731 | 913050 |



Rychlý blokovací systém čelistí



## Serie 9100T



| Ref.   | A   | B   | C   | ⚖️   |        |        |
|--------|-----|-----|-----|------|--------|--------|
| 9120T  | 200 | 210 | 280 | 8,0  | 912031 | 912050 |
| 9120LT | 380 | 200 | 280 | 14,5 | 912031 | 912060 |

## Serie 9100

### Náhradní díly

#### Čelisti

|        | P    | R    | E  | e   |
|--------|------|------|----|-----|
| 912050 | 16,5 | 30,5 | 12 | 3,5 |
| 912060 | 24   | 35,5 | 20 | 6   |
| 913050 | 24   | 35,5 | 21 | 6   |

Obsahuje šroub s podložkou

#### Husillos

#### Spindles

|        | €/u.  | R             | C    | P |
|--------|-------|---------------|------|---|
| 912031 | 44,20 | M22 x 2 x 317 | ⬡ 26 |   |
| 131731 | 62,30 | M27 x 2 x 377 | ⬡ 27 |   |

+ Všechny verze

